

MANGIS MOTOR SERVICE CO.

INVENTORY-	FEDERAL MOGUL SEALS AND BEARINGS	PRICE SHEET 3/5/01			
PART NUMBER	INVENTORY DATE	9/18/2001	Grand Total	Entire Line	\$ 5,604.99
PART NUMBER	BRAND	POP CODE	QUANTITY	JOBB EA	JOBB TOTAL
	OIL SEALS				
1012N	NATIONAL	N	2	\$ 3.21	\$6.42
1165	NATIONAL	OBS	2	\$ 4.00	\$ 8.00
1183	NATIONAL	IC	1	\$ 2.36	\$ 2.36
1188	NATIONAL	IB	1	\$ 2.77	\$ 2.77
1195	NATIONAL	IW	1	\$ 2.31	\$ 2.31
1196	NATIONAL	IA	2	\$ 2.34	\$ 4.68
1209	NATIONAL	ID	1	\$ 4.20	\$ 4.20
1883	NATIONAL	IB	1	\$ 3.79	\$ 3.79
1884	NATIONAL	IB	1	\$ 4.20	\$ 4.20
1949	NATIONAL	IC	2	\$ 3.65	\$ 7.30
1950	NATIONAL	IA	2	\$ 2.89	\$ 5.78
1962	NATIONAL	IA	2	\$ 1.76	\$ 3.52
1992	NATIONAL	IB	2	\$ 2.69	\$ 5.38
2002	NATIONAL	IA	3	\$ 3.11	\$ 9.33
2043	NATIONAL	B	7	\$ 4.98	\$ 34.86
2081	NATIONAL	A	4	\$ 5.33	\$ 21.32
2146	NATIONAL	C	1	\$ 6.35	\$ 6.35
2207	NATIONAL	OBS	2	\$ 7.51	\$ 15.02
2506	NATIONAL	D	2	\$ 5.96	\$ 11.92
2655	NATIONAL	W	1	\$ 7.65	\$ 7.65
2658	NATIONAL	D	1	\$ 6.58	\$ 6.58
2669	NATIONAL	OBS	1	\$ 5.00	\$ 5.00
2689S	NATIONAL	D	1	\$ 11.68	\$ 11.68
2692	NATIONAL	C	2	\$ 6.68	\$ 13.36
2942	NATIONAL	D	0	\$ 6.40	\$ -
2955	NATIONAL	D	1	\$ 10.36	\$ 10.36
3051N	NATIONAL	N	1	\$ 8.68	\$ 8.68
3083	NATIONAL	NA	1	\$ 5.89	\$ 5.89
3087	NATIONAL	A	2	\$ 5.66	\$ 11.32
3103	NATIONAL	C	1	\$ 12.03	\$ 12.03
3195	NATIONAL	B	1	\$ 1.00	\$ 1.00
3214	NATIONAL	NA	2	\$ 5.21	\$ 10.42
3227	NATIONAL	B	2	\$ 3.00	\$ 6.00
3357	NATIONAL	C	2	\$ 2.34	\$ 4.68
3385	NATIONAL	W	2	\$ 19.76	\$ 39.52
3393	NATIONAL	NA	1	\$ 10.98	\$ 10.98
3543	NATIONAL	B	2	\$ 4.70	\$ 9.40
3604	NATIONAL	B	1	\$ 9.86	\$ 9.86
3618	NATIONAL	NA	1	\$ 6.31	\$ 6.31
3622	NATIONAL	C	1	\$ 6.69	\$ 6.69
3655	NATIONAL	C	1	\$ 7.01	\$ 7.01
3677	NATIONAL	D	2	\$ 4.91	\$ 9.82
3698	NATIONAL	NA	1	\$ 12.56	\$ 12.56
3747	NATIONAL	C	1	\$ 7.99	\$ 7.99
3896	NATIONAL	C	1	\$ 8.08	\$ 8.08
4040N	NATIONAL	W	1	\$ 6.70	\$ 6.70
4072N	NATIONAL	N	1	\$ 10.83	\$ 10.83

MANGIS MOTOR SERVICE CO.

4148	NATIONAL	A	3	\$	4.24	\$	12.72
4160	NATIONAL	A	2	\$	6.94	\$	13.88
4249	NATIONAL	A	2	\$	4.77	\$	9.54
4250	NATIONAL	A	4	\$	3.89	\$	15.56
4539H	NATIONAL	D	1	\$	8.41	\$	8.41
4739	NATIONAL	A	2	\$	1.50	\$	3.00
4740	NATIONAL	C	2	\$	1.25	\$	2.50
4762	NATIONAL	A	2	\$	3.99	\$	7.98
4795V	NATIONAL	B	2	\$	6.70	\$	13.40
5121	NATIONAL	B	2	\$	1.95	\$	3.90
5131	NATIONAL	C	2	\$	7.35	\$	14.70
5203	NATIONAL	NA	1	\$	8.96	\$	8.96
5329 [6465]	NATIONAL	NA	1	\$	13.71	\$	13.71
5697	NATIONAL	W	1	\$	5.64	\$	5.64
5698	NATIONAL	NA	1	\$	8.12	\$	8.12
5778	NATIONAL	B	2	\$	8.80	\$	17.60
5836	NATIONAL	NA	0	\$	13.15	\$	-
6241S	NATIONAL	NA	1	\$	4.47	\$	4.47
6638S	NATIONAL	FC	2	\$	23.04	\$	46.08
6712NA	NATIONAL	B	3	\$	2.82	\$	8.46
6808N	NATIONAL	D	2	\$	11.40	\$	22.80
6815	NATIONAL	A	15	\$	1.88	\$	28.20
6818	NATIONAL	A	1	\$	9.30	\$	9.30
6840S	NATIONAL	W	1	\$	7.35	\$	7.35
6939	NATIONAL	OBS	1	\$	6.00	\$	6.00
6988H	NATIONAL	W	1	\$	7.08	\$	7.08
7013S	NATIONAL	D	1	\$	7.40	\$	7.40
7300S	NATIONAL	C	1	\$	5.45	\$	5.45
7399S	NATIONAL	NA	1	\$	2.88	\$	2.88
7412S	NATIONAL	C	1	\$	4.33	\$	4.33
7457N	NATIONAL	NA	1	\$	14.29	\$	14.29
7486S	NATIONAL	NA	1	\$	8.62	\$	8.62
7503S	NATIONAL	OBS	1	\$	6.00	\$	6.00
7537S	NATIONAL	NA	1	\$	4.81	\$	4.81
7692S	NATIONAL	B	1	\$	5.86	\$	5.86
7721	NATIONAL	OBS	2	\$	7.00	\$	14.00
7934S	NATIONAL	W	2	\$	7.92	\$	15.84
8160S	NATIONAL	W	0	\$	4.93	\$	-
8181NA	NATIONAL	W	1	\$	6.37	\$	6.37
8429S	NATIONAL	NA	1	\$	12.27	\$	12.27
8460N	NATIONAL	C	1	\$	5.98	\$	5.98
8516N	NATIONAL	C	1	\$	7.49	\$	7.49
8594S	NATIONAL	NA	2	\$	11.14	\$	22.28
8609	NATIONAL	NA	1	\$	2.85	\$	2.85
8610	NATIONAL	C	0	\$	8.35	\$	-
8611N	NATIONAL	C	1	\$	8.85	\$	8.85
8622	NATIONAL	D	1	\$	11.51	\$	11.51
8660S	NATIONAL	A	2	\$	1.79	\$	3.58
8695S	NATIONAL	D	3	\$	7.86	\$	23.58
8704S	NATIONAL	W	5	\$	8.52	\$	42.60
8705S	NATIONAL	B	2	\$	1.90	\$	3.80

MANGIS MOTOR SERVICE CO.

8835S	NATIONAL	A	2	\$	2.17	\$	4.34
8871	NATIONAL	A	23	\$	1.50	\$	34.00
8907	NATIONAL	NA	0	\$	9.15	\$	-
8912S	NATIONAL	OBS	1	\$	7.00	\$	7.00
8935S	NATIONAL	NA	1	\$	4.78	\$	4.78
8940S	NATIONAL	Z	2	\$	10.32	\$	20.64
8975S	NATIONAL	C	2	\$	5.13	\$	10.26
9015S	NATIONAL	D	2	\$	5.82	\$	11.64
9150S	NATIONAL	C	2	\$	6.35		\$12.70
9161	NATIONAL	NA	1	\$	10.25	\$	10.25
9190N	NATIONAL	OBS	1	\$	8.00	\$	8.00
9316	NATIONAL	B	1	\$	9.11	\$	9.11
9363S	NATIONAL	NA	2	\$	1.96	\$	3.92
9406S	NATIONAL	W	2	\$	5.80	\$	11.60
9449	NATIONAL	B	2	\$	3.05	\$	6.10
9568	NATIONAL	D	2	\$	5.23	\$	10.46
9569S	NATIONAL	D	4	\$	5.02	\$	20.08
9613S	NATIONAL	A	1	\$	1.75	\$	1.75
9762S	NATIONAL	OBS	1	\$	8.00	\$	8.00
9845	NATIONAL	B	2	\$	5.91	\$	11.82
9864S	NATIONAL	A	8	\$	4.89	\$	39.12
40101S	NATIONAL	NA	2	\$	5.43	\$	10.86
41257	NATIONAL	W	1	\$	4.84	\$	4.84
45637S	NATIONAL	NA	1	\$	16.17	\$	16.17
51098	NATIONAL	B	2	\$	3.32	\$	6.64
203006	NATIONAL	W	2	\$	6.03	\$	12.06
203012	NATIONAL	NA	2	\$	5.32	\$	10.64
203013	NATIONAL	C	2	\$	4.34	\$	8.68
203016	NATIONAL	NA	2	\$	6.94	\$	13.88
203025	NATIONAL	B	3	\$	3.34	\$	10.02
203029	NATIONAL	C	2	\$	3.55	\$	7.10
203034	NATIONAL	W	2	\$	6.53	\$	13.06
204017	NATIONAL	TB	4	\$	3.15	\$	12.60
205015	NATIONAL	W	2	\$	4.76	\$	9.52
224015	NATIONAL	IB	0	\$	3.08	\$	-
224045	NATIONAL	IC	0	\$	3.93	\$	-
224255	NATIONAL	IW	1	\$	4.33	\$	4.33
224820	NATIONAL	IA	1	\$	2.73	\$	2.73
292594	NATIONAL	Z	2	\$	5.54	\$	11.08
331107N	NATIONAL	B	1	\$	3.37	\$	3.37
331227H	NATIONAL	D	1	\$	7.99	\$	7.99
331228H	NATIONAL	C	1	\$	8.29	\$	8.29
335924N	NATIONAL	NA	1	\$	21.83	\$	21.83
345035	NATIONAL	NA	2	\$	14.76	\$	29.52
370054A	NATIONAL	FC	1	\$	17.72	\$	17.72
370124A	NATIONAL	FB	2	\$	27.56	\$	55.12
410085	NATIONAL	D	1	\$	7.60	\$	7.60
410190	NATIONAL	NA	2	\$	5.96	\$	11.92
410308	NATIONAL	D	1	\$	6.01	\$	6.01
415960	NATIONAL	B	0	\$	-	\$	-
416273	NATIONAL	D	2	\$	6.01	\$	12.02

MANGIS MOTOR SERVICE CO.

417158	NATIONAL	B	2	\$	7.95	\$	15.90
417531	NATIONAL	NA	0	\$	28.80	\$	-
441130	NATIONAL	TW	2	\$	2.37	\$	4.74
441319	NATIONAL	D	2	\$	3.38	\$	6.76
442251	NATIONAL	B	2	\$	3.87	\$	7.74
442380	NATIONAL	D	1	\$	5.05	\$	5.05
442874	NATIONAL	D	2	\$	6.34	\$	12.68
450041	NATIONAL	OBS	2	\$	4.00	\$	8.00
450061	NATIONAL	OBS	1	\$	5.00	\$	5.00
450076	NATIONAL	NA	2	\$	5.75	\$	11.50
450115	NATIONAL	NA	1	\$	7.55	\$	7.55
450163	NATIONAL	OBS	4	\$	4.00	\$	16.00
450185	NATIONAL	TC	2	\$	6.86	\$	13.72
450194	NATIONAL	NA	1	\$	6.58	\$	6.58
450365	NATIONAL	NA	1	\$	7.17	\$	7.17
450369	NATIONAL	NA	0	\$	6.66	\$	-
450400	NATIONAL	TD	1	\$	4.97	\$	4.97
455147	NATIONAL	NA	1	\$	8.61	\$	8.61
455154	NATIONAL	NA	1	\$	12.36	\$	12.36
456494	NATIONAL	OBS	2	\$	5.00	\$	10.00
470358	NATIONAL	NA	1	\$	7.24	\$	7.24
470361	NATIONAL	B	2	\$	4.72	\$	9.44
470380	NATIONAL	TB	1	\$	2.69	\$	2.69
470543	NATIONAL	NA	1	\$	7.41	\$	7.41
470895	NATIONAL	NA	2	\$	2.98	\$	5.96
471271	NATIONAL	A	2	\$	2.95	\$	5.90
471413	NATIONAL	TA	3	\$	3.77	\$	11.31
471984	NATIONAL	TW	2	\$	8.37	\$	16.74
472394	NATIONAL	TD	2	\$	6.93	\$	13.86
472636	NATIONAL	TD	1	\$	6.48	\$	6.48
472856	NATIONAL	W	1	\$	9.35	\$	9.35
473467	NATIONAL	NA	1	\$	7.84	\$	7.84
473476	NATIONAL	NA	2	\$	9.03	\$	18.06
473560N	NATIONAL	W	1	\$	5.59	\$	5.59
474134	NATIONAL	IA	1	\$	3.36	\$	3.36
475458	NATIONAL	D	1	\$	9.50	\$	9.50
481837	NATIONAL	C	2	\$	3.43	\$	6.86
482163N	NATIONAL	C	1	\$	3.75	\$	3.75
482208	NATIONAL	W	1	\$	3.88	\$	3.88
483488	NATIONAL	W	1	\$	4.84	\$	4.84
485497	NATIONAL	NA	1	\$	16.53	\$	16.53
492702	NATIONAL	NA	2	\$	5.00	\$	10.00
493291	NATIONAL	C	2	\$	7.52	\$	15.04
493637	NATIONAL	C	2	\$	5.73	\$	11.46
710067	NATIONAL	C	1	\$	7.13	\$	7.13
710105	NATIONAL	C	2	\$	6.55	\$	13.10
710167	NATIONAL	NA	0	\$	8.02	\$	-
712146	NATIONAL	D	3	\$	6.31	\$	18.93
722108	NATIONAL	C	1	\$	2.65	\$	2.65
722109	NATIONAL	C	1	\$	4.82	\$	4.82
NATIONAL OIL SEALS			TOTAL	\$	1,948.35	\$	1,948.35

MANGIS MOTOR SERVICE CO.

FRICITION BEARINGS

A1	B C A	A	2	\$	5.47	\$	10.94
SBK1	B C A	A	4	\$	7.95	\$	31.80
A2	B C A	A	4	\$	5.33	\$	21.32
SBK2	B C A	D	2	\$	9.41	\$	18.82
A3	B C A	A	2	\$	6.83	\$	13.66
A4	B C A	A	4	\$	6.31	\$	25.24
A5	B C A	A	2	\$	7.44	\$	14.88
A6	B C A	A	4	\$	6.25	\$	25.00
A7	B C A	D	1	\$	23.32	\$	23.32
A7LK	B C A	NA	1	\$	10.27	\$	10.27
A7RK	B C A	NA	1	\$	11.00	\$	11.00
A9	B C A	B	1	\$	20.88	\$	20.88
A12	B C A	A	2	\$	5.94	\$	11.88
A13	B C A	A	2	\$	6.78	\$	13.56
A14	B C A	A	4	\$	6.32	\$	25.28
A16	B C A	A	2	\$	5.86	\$	11.72
A17	B C A	A	2	\$	6.77	\$	13.54
A18	B C A	A	2	\$	7.21	\$	14.42
A19	B C A	W	2	\$	11.72	\$	23.44
A20	B C A	B	0	\$	30.18	\$	-
A21	B C A	OBS	1	\$	15.00	\$	15.00
A22	B C A	C	1	\$	57.56	\$	57.56
RWP30YYR	B C A	OBS	1	\$	20.00	\$	20.00
A31	B C A	B	2	\$	9.93	\$	19.86
A34	B C A	A	2	\$	6.37	\$	12.74
A35	B C A	A	2	\$	10.81	\$	21.62
A37	B C A	A	2	\$	12.03	\$	24.06
A38	B C A	A	2	\$	12.59	\$	25.18
A39	B C A	A	2	\$	9.79	\$	19.58
B39	B C A	B	1	\$	46.07	\$	46.07
A41	B C A	IA	1	\$	23.24	\$	23.24
B88	B C A	NA	2	\$	3.74	\$	7.48
201FF	B C A	OBS	1	\$	11.24	\$	11.24
202FF	B C A	C	2	\$	11.30	\$	22.60
203FF	B C A	A	1	\$	6.50	\$	6.50
203SS	B C A	B	1	\$	8.25	\$	8.25
204FF	B C A	B	1	\$	12.41	\$	12.41
204SS	B C A	C	1	\$	10.12	\$	10.12
205FFL	B C A	OBS	1	\$	12.22	\$	12.22
205SS	B C A	A	0	\$	9.10	\$	-
206SS	B C A	FB	0	\$	12.81	\$	-
HB206FF	B C A	C	1	\$	22.91	\$	22.91
RW206CCR	B C A	OBS	1	\$	15.00	\$	15.00
207SLB	B C A	NA	1	\$	44.21	\$	44.21
RW207CCRA	B C A	B	0	\$	14.72	\$	-
305L (43305C)	B C A	IW	1	\$	24.19	\$	24.19
306SLVB	B C A	NA	1	\$	39.94	\$	39.94
307L	B C A	C	1	\$	25.03	\$	25.03
362A	B C A	C	1	\$	8.36	\$	8.36

MANGIS MOTOR SERVICE CO.

368A	B C A	C	1	\$	14.77	\$	14.77
387AS	B C A	A	1	\$	13.77	\$	13.77
420	B C A	NA	1	\$	24.81	\$	24.81
453X	B C A	FD	2	\$	12.77	\$	25.54
462	B C A	FW	2	\$	20.77	\$	41.54
MNJ471-S	B C A	B	1	\$	4.30	\$	4.30
493	B C A	FB	2	\$	14.91	\$	29.82
RW508BR	B C A	NA	1	\$	46.80	\$	46.80
1496	B C A	IB	0	\$	14.50	\$	-
1505	B C A	W	0	\$	16.92	\$	-
B1505C	B C A	OBS	1	\$	15.00	\$	15.00
R1558-TAV	B C A	NA	1	\$	22.10	\$	22.10
R1561-TV	B C A	B	1	\$	32.76	\$	32.76
1625T	B C A	NA	1	\$	17.15	\$	17.15
1697C	B C A	W	1	\$	18.00	\$	18.00
CC1705-C	B C A	B	2	\$	12.81	\$	25.62
2065	B C A	B	1	\$	15.20	\$	15.20
2065-31	B C A	W	1	\$	24.25	\$	24.25
FC2255-C	B C A	NA	1	\$	70.10	\$	70.10
2375F	B C A	N	1	\$	29.54	\$	29.54
2420	B C A	W	0	\$	8.84	\$	-
2720	B C A	C	1	\$	5.96	\$	5.96
2755	B C A	NA	1	\$	61.13	\$	61.13
2796	B C A	D	1	\$	14.33	\$	14.33
3984	B C A	FD	1	\$	19.10	\$	19.10
5707	B C A	A	2	\$	11.73	\$	23.46
RP5707	B C A	A	2	\$	21.68	\$	43.36
6408	B C A	A	2	\$	12.23	\$	24.46
RP6408	B C A	B	1	\$	21.68	\$	21.68
0.1496	B C A	IB	1	\$	14.50	\$	14.50
0.2135	B C A	FC	1	\$	37.26	\$	37.26
CA02135-C	B C A	B	1	\$	40.72	\$	40.72
02420-	B C A	W	1	\$	8.84	\$	8.84
0.7204	B C A	D	1	\$	5.87	\$	5.87
0.9067	B C A	C	1	\$	7.80	\$	7.80
0.9081	B C A	NA	1	\$	11.27	\$	11.27
LM119110	B C A	C	2	\$	2.07	\$	4.14
14125A	B C A	TD	5	\$	10.82	\$	54.10
14138A	B C A	TD	1	\$	12.27	\$	12.27
15103S	B C A	B	1	\$	13.32	\$	13.32
15113	B C A	NA	3	\$	11.26	\$	33.78
15123	B C A	B	3	\$	8.16	\$	24.48
15243	B C A	B	1	\$	7.68	\$	7.68
25577	B C A	W	1	\$	15.58	\$	15.58
25581	B C A	NA	5	\$	16.76	\$	83.80
25590	B C A	B	1	\$	11.68	\$	11.68
26882	B C A	W	1	\$	16.09	\$	16.09
28920	B C A	NA	1	\$	14.63	\$	14.63
LM29710	B C A	A	3	\$	6.13	\$	18.39
LM29748	B C A	A	2	\$	11.66	\$	23.32
33821	B C A	NA	3	\$	12.43	\$	37.29

MANGIS MOTOR SERVICE CO.

33895	B C A	NA	1	\$	24.39	\$	24.39
42620	B C A	NA	1	\$	19.21	\$	19.21
L44610	B C A	IB	1	\$	2.17	\$	2.17
57080	B C A	NA	1	\$	11.08	\$	11.08
FC65174	B C A	D	0	\$	8.50	\$	-
FC65354	B C A	B	1	\$	4.11	\$	4.11
FC65662	B C A	A	1	\$	9.01	\$	9.01
LM67010	B C A	B	3	\$	2.60	\$	7.80
HB88107-A	B C A	A	1	\$	21.53	\$	21.53
88128-RA	B C A	C	2	\$	27.34	\$	54.68
88505	B C A	FC	1	\$	24.76	\$	24.76
88508	B C A	W	0	\$	37.00	\$	-
HB88508-A	B C A	D	1	\$	26.49	\$	26.49
HM89410	B C A	C	4	\$	7.22	\$	28.88
HM89411	B C A	W	1	\$	13.81	\$	13.81
HM89443	B C A	D	1	\$	19.54	\$	19.54
HM89446	B C A	W	2	\$	18.24	\$	36.48
LM102949	B C A	A	1	\$	8.75	\$	8.75
JLM104910	B C A	A	2	\$	5.51	\$	11.02
LM104911	B C A	B	4	\$	5.24	\$	20.96
LM104949	B C A	A	2	\$	9.14	\$	18.28
A200349Z	B C A	OBS	1	\$	12.00	\$	12.00
HM212049	B C A	FA	1	\$	20.57	\$	20.57
LM501310	B C A	B	1	\$	3.67	\$	3.67
LM501311	B C A	NA	1	\$	8.21	\$	8.21
LM501314	B C A	A	2	\$	4.33	\$	8.66
LM501349	B C A	A	2	\$	8.80	\$	17.60
513014	B C A	A	1	\$	31.07	\$	31.07
513016-K	B C A	B	1	\$	92.77	\$	92.77
513017-K	B C A	B	1	\$	83.03	\$	83.03
513067	B C A	C	2	\$	22.75	\$	45.50
513074	B C A	NA	1	\$	69.45	\$	69.45
514003	B C A	B	1	\$	21.54	\$	21.54
518500	B C A	C	1	\$	68.10	\$	68.10
518501	B C A	C	1	\$	67.42	\$	67.42
518502	B C A	B	1	\$	67.72	\$	67.72
518503	B C A	NA	0	\$	68.76	\$	-
LM603011	B C A	B	2	\$	5.04	\$	10.08
LM603049	B C A	B	2	\$	8.91	\$	17.82
614007	B C A	B	1	\$	22.72	\$	22.72
614009	B C A	C	2	\$	31.71	\$	63.42
614013	B C A	C	2	\$	28.89	\$	57.78
614014	B C A	A	3	\$	23.63	\$	70.89
614018	B C A	A	1	\$	21.68	\$	21.68
614019	B C A	NA	1	\$	28.00	\$	28.00
614020	B C A	W	1	\$	27.30	\$	27.30
614036	B C A	B	1	\$	28.40	\$	28.40
614040	B C A	B	1	\$	31.69	\$	31.69
614037	B C A	B	0	\$	28.43	\$	-
614054	B C A	W	1	\$	29.00	\$	29.00
614061	B C A	B	2	\$	30.99	\$	61.98

MANGIS MOTOR SERVICE CO.

614083	B C A	A	1	\$	22.94	\$	22.94	
614108	B C A	B	1	\$	30.57	\$	30.57	
614126	B C A	IB	1	\$	21.56	\$	21.56	
JM716610	B C A	FD	1	\$	18.13	\$	18.13	
M804049	B C A	D	2	\$	17.36	\$	34.72	
HM807046	B C A	TPR	1	\$	33.81	\$	33.81	
		B C A BEARINGS			TOTAL	\$	3,656.64	\$ 3,656.64
					LINE TOTAL			\$ 5,604.99

MANGIS MOTOR SERVICE CO.

MANGIS MOTOR SERVICE CO.

MANGIS MOTOR SERVICE CO.

MANGIS MOTOR SERVICE CO.

