

MANGIS MOTOR SERVICE CO.

INVENTORY- RAYBESTOS BRAKES FROM PRICE SHEET NOV 13 2000
 Inventory Date 8/24/2001 Grand Total Entire Line At Jobber \$ 16,740.70
 PART NUMBER BRAND POP CODE QUANTITY JOBB EA CORE JOBB TOTAL

RAYBESTOS BRAKES
 FRICTION AND HYDRAULIC BRAKE PARTS

RPD11	W		1	\$	19.75	\$	19.75
RRD20	WT		1	\$	27.75	\$	27.75
PGD21	WI		1	\$	17.80	\$	17.80
RRD33	W		1	\$	17.95	\$	17.95
PGD36R	FW		1	\$	19.20	\$	19.20
PGD39R	W		1	\$	19.20	\$	19.20
RPD40	XI		1	\$	13.95	\$	13.95
RPD42	WI		1	\$	13.65	\$	13.65
PGD44	FWI		1	\$	14.90	\$	14.90
RPD48	WI		1	\$	14.10	\$	14.10
SSRD50	A		1	\$	36.80	\$	36.80
RPD50M	A		1	\$	12.65	\$	12.65
RRD50	B		1	\$	11.15	\$	11.15
PGD52M	AA		0	\$	25.95	\$	-
RRD52M	AA		3	\$	12.60	\$	37.80
RRD52	A		0	\$	11.15	\$	-
RPD54A	WI		1	\$	14.70	\$	14.70
RPD68	XI		2	\$	15.40	\$	30.80
RRD84	C		1	\$	11.60	\$	11.60
RRD90	W		1	\$	16.15	\$	16.15
RRD91	C		1	\$	15.90	\$	15.90
RPD96	BI		1	\$	11.15	\$	11.15
RPD108	XI		1	\$	14.45	\$	14.45
RPD110	0-2		1	\$	15.75	\$	15.75
RPD112	WI		1	\$	13.95	\$	13.95
RPD117	CI		1	\$	13.45	\$	13.45
RRD119	0-1		1	\$	14.30	\$	14.30
RPD120M	AT		1	\$	21.10	\$	21.10
PGD123M	B		1	\$	34.70	\$	34.70
RRD123	B		1	\$	13.50	\$	13.50
RPD130	BI		1	\$	13.50	\$	13.50
RPD133	0-2		1	\$	11.25	\$	11.25
RPD136	BI		1	\$	14.25	\$	14.25
RPD137	ATI		1	\$	11.95	\$	11.95
RPD139	W		1	\$	15.75	\$	15.75
RRD149	CT		1	\$	15.60	\$	15.60
RRD150	C		1	\$	15.75	\$	15.75
RRD152M	C		1	\$	16.95	\$	16.95
RRD152	C		1	\$	15.75	\$	15.75
RRD153M	BT		1	\$	15.75	\$	15.75
RRD154M	AA		1	\$	11.85	\$	11.85
RRD154	A		1	\$	10.85	\$	10.85
RPD160	XI		1	\$	16.55	\$	16.55
RPD166	CI		1	\$	15.45	\$	15.45
RPD169	0-1		1	\$	12.75	\$	12.75

MANGIS MOTOR SERVICE CO.

RPD170M	B	1	\$	15.55	\$	15.55
RRD170	B	1	\$	14.25	\$	14.25
RPD177	CI	1	\$	15.55	\$	15.55
RPD178	WI	1	\$	14.10	\$	14.10
RRD179	C	1	\$	15.35	\$	15.35
RRD183M	B	1	\$	12.65	\$	12.65
RRD183H	C	1	\$	12.10	\$	12.10
PGD190M	C	1	\$	26.25	\$	26.25
RRD190M	C	1	\$	12.40	\$	12.40
RPD191	W	2	\$	22.70	\$	45.40
					\$	-
RRD199M	C	1	\$	16.80	\$	16.80
RRD199	B	1	\$	14.75	\$	14.75
RRD203M	B	1	\$	12.75	\$	12.75
RPD207	AI	1	\$	11.15	\$	11.15
RPD214M	C	2	\$	15.75	\$	31.50
PGD215M	AA	2	\$	26.45	\$	52.90
RPD215M	AA	1	\$	12.75	\$	12.75
PGD218M	CI	1	\$	27.95	\$	27.95
RRD219M	B	2	\$	12.30	\$	24.60
RRD220M	B	2	\$	12.70	\$	25.40
RRD221M	B	1	\$	12.50	\$	12.50
PGD224M	CT	1	\$	69.95	\$	69.95
RPD242M	AAI	0	\$	12.65	\$	-
RPD242	AI	2	\$	12.05	\$	24.10
RRD249M	BI	2	\$	16.65	\$	33.30
RPD256M	A	1	\$	18.45	\$	18.45
PGD257R	B	1	\$	20.35	\$	20.35
RRD257M	AT	1	\$	13.65	\$	13.65
RRD259M	W	1	\$	13.65	\$	13.65
RPD261M	W	1	\$	19.95	\$	19.95
PGD262M	C	1	\$	34.15	\$	34.15
RPD262M	C	1	\$	15.05	\$	15.05
RRD269M	AT	1	\$	15.35	\$	15.35
RPD272	BI	1	\$	11.40	\$	11.40
RPD275M	AAI	1	\$	14.35	\$	14.35
RPD289M	AA	2	\$	12.65	\$	25.30
RPD297	CI	1	\$	14.55	\$	14.55
RPD299	BI	1	\$	15.50	\$	15.50
RRD310M	B	1	\$	13.05	\$	13.05
RRD310H	B	1	\$	12.95	\$	12.95
RPD319M	AI	1	\$	18.85	\$	18.85
RPD320M	ATI	0	\$	16.95	\$	-
RPD323	AI	1	\$	13.75	\$	13.75
PGD324M	B	1	\$	34.65	\$	34.65
RRD324M	B	1	\$	14.10	\$	14.10
RPD326M	CT	1	\$	20.50	\$	20.50
RPD329	AI	1	\$	18.95	\$	18.95
RPD334M	AAI	1	\$	15.25	\$	15.25
RRD344M	AAI	1	\$	18.90	\$	18.90
RRD346M	C	1	\$	28.60	\$	28.60

MANGIS MOTOR SERVICE CO.

PGD347R	B	1	\$	24.95	\$	24.95
RRD347	B	1	\$	15.50	\$	15.50
RPD353M	B	1	\$	16.35	\$	16.35
RPD354M	C	1	\$	15.05	\$	15.05
RPD356M	AAI	1	\$	13.10	\$	13.10
RRD367M	CT	1	\$	19.75	\$	19.75
RPD368M	AT	1	\$	16.90	\$	16.90
PGD369M	AAT	1	\$	34.15	\$	34.15
RPD369M	AT	1	\$	21.15	\$	21.15
RPD370M	AT	1	\$	17.95	\$	17.95
RPD375M	AAT	1	\$	13.50	\$	13.50
PGD376M	AA	1	\$	36.65	\$	36.65
RPD376M	A	1	\$	16.45	\$	16.45
PGD377M	A	1	\$	36.30	\$	36.30
RPD377M	C	1	\$	17.65	\$	17.65
RPD378M	C	1	\$	17.85	\$	17.85
					\$	-
RRD385M	C	1	\$	18.95	\$	18.95
RPD386M	C	1	\$	23.45	\$	23.45
RPD399M	B	1	\$	16.10	\$	16.10
PGD414M	C	1	\$	33.05	\$	33.05
RPD415M	C	1	\$	19.35	\$	19.35
RRD417M	B	1	\$	16.15	\$	16.15
RRD421M	A	1	\$	16.50	\$	16.50
RRD421AM	A	1	\$	16.50	\$	16.50
PGD450M	BT	1	\$	39.55	\$	39.55
PGD459M	BT	1	\$	23.20	\$	23.20
RPD465	AAI	1	\$	17.40	\$	17.40
RPD466M	AI	1	\$	15.10	\$	15.10
PGD468M	BI	1	\$	23.65	\$	23.65
PGD473M	AI	1	\$	31.25	\$	31.25
RPD477M	AT	1	\$	17.65	\$	17.65
RRD478M	C	1	\$	19.45	\$	19.45
PGD499R	B	1	\$	31.60	\$	31.60
PGD499AM	B	1	\$	36.40	\$	36.40
PGD499AR	C	1	\$	33.55	\$	33.55
RPD505M	A	1	\$	16.35	\$	16.35
PGD506M	AA	2	\$	30.25	\$	60.50
RPD506M	AA	1	\$	18.35	\$	18.35
RPD508M	B	1	\$	17.75	\$	17.75
PGD522M	A	1	\$	33.95	\$	33.95
RPD522M	A	1	\$	16.25	\$	16.25
PGD524M	AA	1	\$	33.95	\$	33.95
RPD524M	AA	1	\$	16.15	\$	16.15
RPD529M	CT	1	\$	19.95	\$	19.95
PGD544R	A	1	\$	28.95	\$	28.95
RPD557M	NBT	1	\$	54.25	\$	54.25
RRD591M	B	1	\$	18.85	\$	18.85
PGD598	C	1	\$	34.35	\$	34.35
PG601	B	1	\$	33.90	\$	33.90
RP601M	B	0	\$	22.95	\$	-

MANGIS MOTOR SERVICE CO.

PGD614AM	C	1	\$	40.25		\$	40.25
RPD623M	B	1	\$	21.55		\$	21.55
PGD628M	C	1	\$	35.95		\$	35.95
PGD632M	AT	1	\$	22.90		\$	22.90
RPD637	C	1	\$	19.90		\$	19.90
PGD641M	BRAKE S-C	1	\$	30.45		\$	30.45
RPD652M	BT	1	\$	19.95		\$	19.95
RPD679M	AT	1	\$	25.95		\$	25.95
				SUB TOTAL		\$	3,129.85
						\$	3,129.85

9RP USE55RR	O-2	1	\$	15.35	\$	-	\$	15.35
33A RR	CT	1	\$	30.95	\$	-	\$	30.95
114RP	CT	1	\$	16.25	\$	6.00	\$	22.25
141RP	W	1	\$	21.45	\$	-	\$	21.45
151RP	C	1	\$	10.65	\$	-	\$	10.65
152RP	C	1	\$	10.55	\$	6.00	\$	16.55
169RP	C	1	\$	10.80	\$	-	\$	10.80
176RP (326RP)	FW	1	\$	20.25	\$	6.00	\$	26.25
227RR	W	1	\$	18.55	\$	-	\$	18.55
228RP	C	1	\$	10.60	\$	6.00	\$	16.60
241RR	C	1	\$	16.65	\$	-	\$	16.65
242RP	AA	1	\$	10.80	\$	6.00	\$	16.80
246RR	W	1	\$	17.85	\$	6.00	\$	23.85
248RP	CT	1	\$	14.25	\$	6.00	\$	20.25
260RR	W	1	\$	18.65	\$	-	\$	18.65
263RR	AA	1	\$	18.10	\$	6.00	\$	24.10
263RP	AA	1	\$	10.80	\$	6.00	\$	16.80
265RP	C	1	\$	11.10	\$	12.00	\$	23.10
268RP	FWI	1	\$	13.85	\$	-	\$	13.85
280RR	CT	1	\$	16.40	\$	6.00	\$	22.40
280RP	CT	1	\$	10.85	\$	6.00	\$	16.85
314RR	AAT	1	\$	35.60	\$	12.00	\$	47.60
315RP	CTI	2	\$	13.45	\$	-	\$	26.90
316RR	AT	1	\$	33.60	\$	12.00	\$	45.60
321RR	WT	1	\$	90.95	\$	36.00	\$	126.95
330RP	W	1	\$	16.55	\$	-	\$	16.55
333RP	C	1	\$	14.85	\$	-	\$	14.85
335RP	W	1	\$	15.75	\$	-	\$	15.75
343RP	0-1	1	\$	13.55	\$	-	\$	13.55
344PG	FWI	1	\$	14.65	\$	-	\$	14.65
348RP	FW	1	\$	15.45	\$	-	\$	15.45
359RP	FWI	1	\$	13.15	\$	-	\$	13.15
363RP	C	1	\$	10.80	\$	-	\$	10.80
371PG	FWI	1	\$	14.95	\$	-	\$	14.95
372PG	WI	1	\$	15.65	\$	-	\$	15.65
392RP	WI	1	\$	13.45	\$	-	\$	13.45
394RP	0-1	1	\$	14.55	\$	-	\$	14.55
395RP	WT	1	\$	13.35	\$	-	\$	13.35
396RP	0-1	1	\$	14.95	\$	-	\$	14.95
407RP	AI	1	\$	13.95	\$	6.00	\$	19.95

MANGIS MOTOR SERVICE CO.

408RP	0-1	1	\$	13.45	\$	6.00	\$	19.45
417PG	FWT	1	\$	55.95	\$	6.00	\$	61.95
428RP	WI	1	\$	13.35	\$	6.00	\$	19.35
440RP	0-1	1	\$	13.15	\$	6.00	\$	19.15
445RR	B	1	\$	16.30	\$	6.00	\$	22.30
446RP	B	1	\$	10.60	\$	24.00	\$	34.60
449RR	BT	2	\$	21.15	\$	24.00	\$	90.30
449RP	BT	1	\$	14.10	\$	6.00	\$	20.10
450RR	CT	1	\$	22.50	\$	6.00	\$	28.50
451RR	AT	1	\$	47.50	\$	24.00	\$	71.50
452RR	AT	1	\$	59.50	\$	24.00	\$	83.50
453PG	FWI	1	\$	17.45	\$	-	\$	17.45
462RP	A	1	\$	10.80	\$	6.00	\$	16.80
465PG	FWI	1	\$	16.95	\$	-	\$	16.95
472RP	B	0	\$	11.15	\$	6.00	\$	-
473RR	AAT	1	\$	22.25	\$	12.00	\$	34.25
474RR	A	1	\$	16.50	\$	6.00	\$	22.50
474RP	A	1	\$	10.80	\$	6.00	\$	16.80
477RP	FW	1	\$	13.45	\$	-	\$	13.45
479RP	CI	1	\$	13.25	\$	-	\$	13.25
481RP	B	1	\$	10.80	\$	6.00	\$	16.80
482RR	C	1	\$	16.75	\$	6.00	\$	22.75
498RP	FWT	1	\$	14.75	\$	-	\$	14.75
500RP	C	1	\$	16.50	\$	6.00	\$	22.50
501RP	AA	1	\$	11.15	\$	6.00	\$	17.15
502RP	WI	1	\$	13.45	\$	-	\$	13.45
504RP	W	1	\$	19.55	\$	-	\$	19.55
505RP	ATI	1	\$	13.90	\$	6.00	\$	19.90
514RP	AA	1	\$	10.80	\$	6.00	\$	16.80
517RP	AI	1	\$	13.45	\$	6.00	\$	19.45
519RP	AA	1	\$	11.35	\$	6.00	\$	17.35
520RP	B	1	\$	15.85	\$	6.00	\$	21.85
521RR	C	1	\$	16.70	\$	-	\$	16.70
522RP	C	1	\$	10.55	\$	-	\$	10.55
523RP	BTI	1	\$	13.50	\$	6.00	\$	19.50
524RP	CTI	1	\$	14.95	\$	6.00	\$	20.95
531RP	AI	1	\$	13.50	\$	6.00	\$	19.50
533RP	AI	1	\$	10.55	\$	6.00	\$	16.55
538RP	AAT	1	\$	14.95	\$	6.00	\$	20.95
545RP	CI	1	\$	14.15	\$	6.00	\$	20.15
546RP	AAI	2	\$	12.95	\$	6.00	\$	37.90
551RP	AAI	1	\$	10.65	\$	6.00	\$	16.65
552RR	AA	1	\$	17.60	\$	6.00	\$	23.60
553RR	AA	1	\$	16.30	\$	6.00	\$	22.30
554RPUSE619RP	0-2	1	\$	13.45	\$	-	\$	13.45
564RR	A	1	\$	18.95	\$	6.00	\$	24.95
565RP	BTI	1	\$	14.25	\$	6.00	\$	20.25
566RR	A	1	\$	19.25	\$	6.00	\$	25.25
567RR	C	2	\$	19.75	\$	6.00	\$	51.50
575RP	AI	1	\$	15.35	\$	6.00	\$	21.35
577RP	C	1	\$	15.65	\$	-	\$	15.65

MANGIS MOTOR SERVICE CO.

580RR	C	1	\$	19.20	\$	6.00	\$	25.20	
581RR	AAT	1	\$	16.40	\$	12.00	\$	28.40	
582RP	AT	1	\$	17.55	\$	12.00	\$	29.55	
583RR	AT	1	\$	38.25	\$	24.00	\$	62.25	
593RP	AT	1	\$	17.25	\$	12.00	\$	29.25	
594PG	C	1	\$	18.45	\$	6.00	\$	24.45	
595RP	W	1	\$	15.65	\$	-	\$	15.65	
597RP	AAI	1	\$	13.65	\$	6.00	\$	19.65	
598RP	B	1	\$	15.10	\$	6.00	\$	21.10	
599RP	A	1	\$	20.95	\$	6.00	\$	26.95	
618RP	B	1	\$	21.95	\$	12.00	\$	33.95	
629RP	A	1	\$	13.10	\$	6.00	\$	19.10	
636RP	A	1	\$	17.20	\$	6.00	\$	23.20	
659PG	AAI	1	\$	15.15	\$	6.00	\$	21.15	
670RP	CT	1	\$	15.70	\$	6.00	\$	21.70	
675RP	BT	1	\$	20.65	\$	12.00	\$	32.65	
				SUB TOTAL			\$	2,567.70	\$ 2,567.70

DISC PAD SHIM KITS

DS8000	C	1	\$	6.29		\$	6.29		
DS8094	A	1	\$	7.39		\$	7.39		
DS8131	W	1	\$	7.39		\$	7.39		
				SUB TOTAL		\$	21.07	\$	21.07

DISC BRAKE ROTORS + BRAKE DRUMS

2660	W	1	\$	61.25		\$	61.25		
5006	A	2	\$	49.15		\$	98.30		
5061	AA	1	\$	24.86		\$	24.86		
.10-5061	RAYMLD AA	1	\$	9.31		\$	9.31		
.10-5072	RAYMLD A	2	\$	9.74		\$	19.48		
6000	B	1	\$	36.44		\$	36.44		
.10-6082	RAYMLD A	1	\$	8.93		\$	8.93		
6886	AA	2	\$	32.54		\$	65.08		
7011	AT	0	\$	36.85		\$	-		
.10-7011	RAYMLD A	1	\$	10.85		\$	10.85		
7032	C	2	\$	51.20		\$	102.40		
.10-66204	RAYMLD A	1	\$	19.79		\$	19.79		
.10-66442	RAYMLD A	2	\$	20.96		\$	41.92		
.10-66492	RAYMLD A	1	\$	20.96		\$	20.96		
						SUBTOTAL	\$	436.90	\$ 436.90

BRAKE CABLES

BC91984	OBS	1	\$	15.00		\$	15.00		
BC92041	OBS	2	\$	15.00		\$	30.00		
BC92672	C	1	\$	20.08		\$	20.08		
						SUBTOTAL	\$	65.08	\$ 65.08

BRAKE HOSES ALSO SEE RAYMOLD 45- Part #

BH4000	BT	1	\$	18.42		\$	18.42		
--------	----	---	----	-------	--	----	-------	--	--

MANGIS MOTOR SERVICE CO.

G-5795	AA	0	\$	0.53		\$	-	
					SUBTOTAL	\$	26.20	
								\$ 26.20
MASTER CYLINDER ASSEMBLIES								
MC10032	OBS	1	\$	125.00		\$	125.00	
MC17917	OBS	1	\$	125.00		\$	125.00	
MC24710	OBS	1	\$	125.00		\$	125.00	
MC27285	OBS	1	\$	125.00		\$	125.00	
MC32068	OBS	1	\$	125.00		\$	125.00	
MC32913	OBS	1	\$	125.00		\$	125.00	
					SUBTOTAL	\$	750.00	
								\$ 750.00
MASTER CYLINDER REPAIR KITS								
MK-1	AAT	1	\$	13.36		\$	13.36	
MK-2	A	1	\$	12.44		\$	12.44	
MK-3	AA	1	\$	12.21		\$	12.21	
MK-25	A	1	\$	13.14		\$	13.14	
MK-33	AAT	1	\$	17.00		\$	17.00	
MK-71	CT	1	\$	16.44		\$	16.44	
MK-100	AA	1	\$	10.28		\$	10.28	
MK-166	AA	1	\$	12.87		\$	12.87	
MK-207	AT	1	\$	11.28		\$	11.28	
MK-208	C	1	\$	19.39		\$	19.39	
MK-222	WT	1	\$	11.32		\$	11.32	
MK-364	B	1	\$	13.68		\$	13.68	
MK-434	OBS	1	\$	15.00		\$	15.00	
MK-441	OBS	1	\$	15.00		\$	15.00	
MK-484	FW	1	\$	19.79		\$	19.79	
MK-514	BI	1	\$	23.57		\$	23.57	
MK-525	WT	1	\$	26.52		\$	26.52	
MK-630	FW	1	\$	20.42		\$	20.42	
MK-663	WT	1	\$	25.73		\$	25.73	
MK-683	FWT	1	\$	19.55		\$	19.55	
MK-685	B	1	\$	23.88		\$	23.88	
MK-689	CT	1	\$	21.89		\$	21.89	
MK-704	CT	1	\$	22.61		\$	22.61	
MK-708	FW	1	\$	20.13		\$	20.13	
MK-754	C	1	\$	23.43		\$	23.43	
MK-790	AI	9	\$	20.58		\$	185.22	
MK-800	AATI	1	\$	10.70		\$	10.70	
MK-830	WT	1	\$	23.64		\$	23.64	
MK-874	AT	1	\$	14.18		\$	14.18	
MK-960	OBS	1	\$	20.00		\$	20.00	
MK-961	B	2	\$	24.59		\$	49.18	
MK1486	A	1	\$	20.80		\$	20.80	
MK-1630	CT	1	\$	20.98		\$	20.98	
					SUBTOTAL	\$	785.63	
								\$ 785.63
S-6446	B	4	\$	1.39		\$	5.56	
S-6858	AA	6	\$	1.54		\$	9.24	

MANGIS MOTOR SERVICE CO.

S-10591	C	10	\$	1.54	\$	15.40	
S-11410	B	11	\$	1.54	\$	16.94	
S-11579	B	10	\$	1.54	\$	15.40	
S-11589	OBS	3	\$	1.54	\$	4.62	
S-11596	C	9	\$	2.15	\$	19.35	
S-20089	B	6	\$	1.33	\$	7.98	
S-22066	C	10	\$	2.05	\$	20.50	
S-22067	CI	10	\$	2.01	\$	20.10	
S-22068	AI	10	\$	1.70	\$	17.00	
S-22069	AAI	8	\$	1.43	\$	11.44	
S-22163	WI	9	\$	3.08	\$	27.72	
S-22430	B	5	\$	1.13	\$	5.65	
S-22660	AA	3	\$	1.15	\$	3.45	
S-24493	B	2	\$	1.46	\$	2.92	
S-33512	C	6	\$	1.64	\$	9.84	
					\$	213.11	
					\$		213.11
SC-37821	A	1	\$	49.80	\$	49.80	
					\$		49.80

WHEEL CYLINDER ASSEMBLIES ALSO SEE RAYMOLD 20- Part #

WC-4803	W	1	\$	33.06	\$	33.06	
WC-7229	OBS	1	\$	30.00	\$	30.00	
WC-7350	FWT	5	\$	52.79	\$	263.95	
WC-7351	FWT	9	\$	52.79	\$	475.11	
WC-13387	B	0	\$	26.21	\$	-	
WC-13388	B	0	\$	26.21	\$	-	
WC-14205	FWT	1	\$	53.82	\$	53.82	
WC-14206	FWT	1	\$	53.82	\$	53.82	
WC-14481	FWT	1	\$	58.66	\$	58.66	
WC-18290	C	1	\$	28.58	\$	28.58	
WC-18291	C	1	\$	28.58	\$	28.58	
WC-18302	FWT	3	\$	32.55	\$	97.65	
WC-18303	FWT	3	\$	32.55	\$	97.65	
WC-19236	W	1	\$	27.14	\$	27.14	
WC-23379	OBS	1	\$	20.00	\$	20.00	
WC-31139	W	1	\$	35.48	\$	35.48	
WC-32071	FW	1	\$	36.57	\$	36.57	
WC-34177	W	1	\$	25.18	\$	25.18	
					\$	-	
WC-36076	C	1	\$	22.09	\$	22.09	
WC-36100	C	1	\$	27.76	\$	27.76	
WC-36277	OBS	1	\$	18.50	\$	18.50	
WC-37029	C	1	\$	19.06	\$	19.06	
WC-37033	CT	0	\$	25.35	\$	-	
WC-37034	CT	0	\$	25.35	\$	-	
WC-37080	A	2	\$	23.33	\$	46.66	
WC-37132	AT	0	\$	23.65	\$	-	
WC-37133	AT	0	\$	23.65	\$	-	
WC-37149	BT	4	\$	28.07	\$	112.28	

MANGIS MOTOR SERVICE CO.

WK-180	OBS	1	\$	10.00	\$	10.00
WK-195	BT	2	\$	9.33	\$	18.66
WK-218	CT	2	\$	13.69	\$	27.38
WK-223	CI	2	\$	5.00	\$	10.00
WK-224	BI	1	\$	5.01	\$	5.01
WK-237	B	2	\$	8.01	\$	16.02
WK-249	B	1	\$	6.10	\$	6.10
WK-264	W	1	\$	6.34	\$	6.34
WK-382	C	2	\$	7.70	\$	15.40
WK-386	W	2	\$	6.95	\$	13.90
WK-396	B	2	\$	5.14	\$	10.28
WK-397	FW	4	\$	6.94	\$	27.76
WK-418	AA	2	\$	5.79	\$	11.58
WK-422	A	2	\$	7.93	\$	15.86
WK-423	A	2	\$	5.45	\$	10.90
WK-445	FWT	2	\$	6.26	\$	12.52
WK-452	C	1	\$	22.96	\$	22.96
WK-453	C	1	\$	23.38	\$	23.38
WK-479	FWT	1	\$	8.75	\$	8.75
WK483	C	2	\$	5.14	\$	10.28
WK-491	A	2	\$	5.79	\$	11.58
WK-513	AI	2	\$	4.91	\$	9.82
WK-515	W	0	\$	13.87	\$	-
WK-523	FW	2	\$	8.69	\$	17.38
WK-524	AA	4	\$	10.04	\$	40.16
WK-610	A	2	\$	4.48	\$	8.96
WK-629	A	2	\$	9.05	\$	18.10
WK-638	B	3	\$	6.23	\$	18.69
WK-643	CTI	2	\$	7.32	\$	14.64
WK-667	ATI	3	\$	8.75	\$	26.25
WK-698	B	2	\$	5.70	\$	11.40
WK-702	AT	2	\$	12.49	\$	24.98
WK-705	BT	4	\$	8.11	\$	32.44
WK-714	AI	1	\$	5.14	\$	5.14
WK-758	CI	2	\$	8.23	\$	16.46
WK-782	FWT	11	\$	3.92	\$	43.12
WK-806	BT	1	\$	7.19	\$	7.19
WK-838	CTI	2	\$	7.78	\$	15.56
WK-846	BI	2	\$	10.14	\$	20.28
WK-854	ATI	2	\$	5.36	\$	10.72
WK-855	BTI	2	\$	4.63	\$	9.26
WK-882	BI	2	\$	4.89	\$	9.78
WK-885	AA	3	\$	8.23	\$	24.69
WK-886	AA	3	\$	7.61	\$	22.83
WK-893	B	1	\$	7.49	\$	7.49
WK-900	W	2	\$	6.75	\$	13.50
WK-935	B	2	\$	7.40	\$	14.80
WK-936	BI	2	\$	9.05	\$	18.10
WK-937	W	1	\$	14.80	\$	14.80
WK-970	W	4	\$	8.50	\$	34.00
WK-1069	A	1	\$	6.35	\$	6.35

MANGIS MOTOR SERVICE CO.

WK-1070	A	2	\$	7.51	\$	15.02	
WK-1099	BI	2	\$	8.19	\$	16.38	
WK-1371	B	2	\$	5.31	\$	10.62	
WK-1412	A	2	\$	5.50	\$	11.00	
WK-1415	C	2	\$	14.40	\$	28.80	
WK-1451	AT	2	\$	6.54	\$	13.08	
WK-1455	CT	1	\$	11.69	\$	11.69	
WK-1537	A	2	\$	7.32	\$	14.64	
WK-1575	A	2	\$	5.33	\$	10.66	
WK-1743	A	2	\$	6.88	\$	13.76	
WK-1951	AT	2	\$	7.28	\$	14.56	
WK-1952	AT	3	\$	7.81	\$	23.43	
				SUBTOTAL	\$	1,164.99	
	A						\$ 1,164.99
	RAYMOLD						

102677	A	0	\$	19.47	\$	-	
105061	A	1	\$	9.31	\$	9.31	
105072	A	2	\$	9.74	\$	19.48	
106082	A	1	\$	8.93	\$	8.93	
107011	A	1	\$	10.85	\$	10.85	
2013387	A	1	\$	5.96	\$	5.96	
2013388	A	1	\$	5.96	\$	5.96	
2017507	A	1	\$	5.59	\$	5.59	
2017508	A	1	\$	5.59	\$	5.59	
2017509	A	1	\$	6.02	\$	6.02	
2017510	A	1	\$	6.02	\$	6.02	
2036058	A	1	\$	7.36	\$	7.36	
2037021	A	2	\$	5.80	\$	11.60	
2037024	A	1	\$	5.23	\$	5.23	
2037048	A	2	\$	5.36	\$	10.72	
2037132	A	1	\$	6.51	\$	6.51	
2037133	A	1	\$	6.51	\$	6.51	
2037235	A	2	\$	6.02	\$	12.04	
2037290	A	2	\$	7.36	\$	14.72	
2037343	A	2	\$	5.59	\$	11.18	
2037529	A	1	\$	5.96	\$	5.96	
2037530	A	1	\$	5.96	\$	5.96	
2037531	A	1	\$	5.80	\$	5.80	
2037535	A	2	\$	7.22	\$	14.44	
2037564	A	2	\$	5.36	\$	10.72	
2037585	A	2	\$	6.65	\$	13.30	
2037591	A	1	\$	5.59	\$	5.59	
2037592	A	2	\$	5.59	\$	11.18	
2037625	A	2	\$	5.25	\$	10.50	
2037640	A	2	\$	6.71	\$	13.42	
2037663	A	2	\$	6.56	\$	13.12	
2037668	A	2	\$	5.96	\$	11.92	
2037677	A	1	\$	5.36	\$	5.36	
2037694	A	2	\$	6.51	\$	13.02	
2037707	A	0	\$	7.93	\$	-	

MANGIS MOTOR SERVICE CO.

2037750	A	2	\$	6.37	\$	12.74
2037778	A	2	\$	6.65	\$	13.30
2037779	A	2	\$	6.23	\$	12.46
2037780	A	0	\$	8.20	\$	-
2037781	A	1	\$	6.94	\$	6.94
2037782	A	0	\$	11.89	\$	-
2037783	A	2	\$	8.36	\$	16.72
2037784	A	2	\$	9.56	\$	19.12
2037787	A	2	\$	8.79	\$	17.58
2037844	A	2	\$	6.08	\$	12.16
2037855	A	2	\$	9.77	\$	19.54
2037856	A	2	\$	8.36	\$	16.72
2037857	A	2	\$	7.22	\$	14.44
4536765	A	1	\$	9.76	\$	9.76
4536847	A	1	\$	6.93	\$	6.93
4536854	A	2	\$	6.62	\$	13.24
4536855	A	1	\$	11.17	\$	11.17
4536935	A	1	\$	8.77	\$	8.77
4536936	A	1	\$	8.77	\$	8.77
4536984	A	1	\$	10.90	\$	10.90
4538045	A	1	\$	10.47	\$	10.47
4538046	A	1	\$	10.47	\$	10.47
4538054	A	1	\$	10.19	\$	10.19
4538074	A	1	\$	7.71	\$	7.71
4538101	A	1	\$	8.20	\$	8.20
4538138	A	1	\$	11.88	\$	11.88
4538178	A	1	\$	8.20	\$	8.20
4538193	A	1	\$	7.03	\$	7.03
4538194	A	1	\$	7.03	\$	7.03
4538262	A	1	\$	11.40	\$	11.40
4538373	A	1	\$	9.76	\$	9.76
4538382	A	1	\$	9.76	\$	9.76
4538421	A	2	\$	6.90	\$	13.80
4538681	A	1	\$	9.76	\$	9.76
4538905	A	1	\$	8.31	\$	8.31
4538906	A	1	\$	8.31	\$	8.31
505548	A	1	\$	5.08	\$	5.08
505552	A	1	\$	2.05	\$	2.05
505610	A	1	\$	3.03	\$	3.03
507055	A	1	\$	3.88	\$	3.88
507071	A	1	\$	4.10	\$	4.10
507168	A	1	\$	4.02	\$	4.02
507169	A	1	\$	4.02	\$	4.02
507209	A	1	\$	5.53	\$	5.53
507249	A	1	\$	3.68	\$	3.68
507250	A	1	\$	3.96	\$	3.96
507267	A	1	\$	3.11	\$	3.11
507268	A	1	\$	4.22	\$	4.22
507269	A	1	\$	3.47	\$	3.47
507270	A	1	\$	4.33	\$	4.33
507276	A	1	\$	6.80	\$	6.80

MANGIS MOTOR SERVICE CO.

507279	A	1	\$	4.10	\$	4.10
507287	A	1	\$	4.79	\$	4.79
	A				\$	-
1066204	A	1	\$	19.79	\$	19.79
1066442	A	2	\$	20.96	\$	41.92
1066492	A	1	\$	20.96	\$	20.96
					\$	-
5017147	A	1	\$	6.91	\$	6.91
5017279	A	1	\$	3.83	\$	3.83
5017326	A	1	\$	3.83	\$	3.83
				SUB TOTAL	\$	860.82
					\$	860.82

RAYBESTOS HARDWARE ALSO SEE RAYMOLD 50- Part Number

H-130	B	0	\$	4.77	\$	-
H-131-2	AA	1	\$	5.12	\$	5.12
H323-2	AA	1	\$	4.71	\$	4.71
H324	AAT		\$	4.36	\$	-
H325	AA	2	\$	4.00	\$	8.00
H336	W	1	\$	4.52	\$	4.52
H337	FWT	2	\$	6.32	\$	12.64
H341	FW	2	\$	5.36	\$	10.72
H345-2	B	1	\$	4.40	\$	4.40
H350	FW	1	\$	6.14	\$	6.14
H351	C	1	\$	4.21	\$	4.21
H412	AA	2	\$	5.81	\$	11.62
H413	C	2	\$	5.26	\$	10.52
H415	A	1	\$	4.64	\$	4.64
H423	AT	1	\$	5.71	\$	5.71
H425	AT	1	\$	4.19	\$	4.19
H428	B	1	\$	6.47	\$	6.47
H446	AAT	1	\$	2.86	\$	2.86
H521	WT	1	\$	6.14	\$	6.14
H605	CT	1	\$	10.67	\$	10.67
H703	W	1	\$	3.60	\$	3.60
H704	OBS	1	\$	4.00	\$	4.00
H1105-2	C	1	\$	1.76	\$	1.76
H1106-2	C	1	\$	0.08	\$	0.08
H1107-2	B	1	\$	1.76	\$	1.76
H1108-2	B	1	\$	1.76	\$	1.76
H1109-2	C	2	\$	1.76	\$	3.52
H1110-2	FW	2	\$	1.76	\$	3.52
H1119-2	CT	1	\$	3.03	\$	3.03
H1132-2	A	1	\$	1.52	\$	1.52
H1135-2	FW	1	\$	1.48	\$	1.48
H1139-2	B	2	\$	1.80	\$	3.60
H1150-2	FW	1	\$	1.56	\$	1.56
H1156-2	C	1	\$	2.01	\$	2.01
H1157-2	WT	2	\$	1.89	\$	3.78
H1164-2	B	0	\$	4.55	\$	-
H1175-2	AA	2	\$	1.87	\$	3.74
H1177-2	B	2	\$	2.15	\$	4.30

MANGIS MOTOR SERVICE CO.

H1187-2	C	1	\$	1.95	\$	1.95
H1300-2	B	2	\$	3.81	\$	7.62
H1338-2	B	1	\$	1.89	\$	1.89
H1414-2	C	2	\$	2.00	\$	4.00
H1418-2	C	2	\$	1.83	\$	3.66
H1421-2	B	3	\$	2.47	\$	7.41
H1422-2	AA	2	\$	2.04	\$	4.08
H1456-2	AA	20	\$	1.35	\$	27.00
H1457-2	A	2	\$	1.89	\$	3.78
H1500-2	AA	2	\$	6.04	\$	12.08
H1520-2	AA	1	\$	6.07	\$	6.07
H1521-2	AA	1	\$	6.07	\$	6.07
H1522-2	AA	1	\$	6.07	\$	6.07
H1523-2	A	1	\$	6.07	\$	6.07
H1526-2	A	2	\$	6.45	\$	12.90
H1527-2	A	1	\$	6.45	\$	6.45
H1530-2	AA	1	\$	6.18	\$	6.18
H1531-2	AA	1	\$	6.18	\$	6.18
H1532-2	B	1	\$	5.73	\$	5.73
H1533-2	B	1	\$	5.73	\$	5.73
H1546-2	AA	1	\$	10.63	\$	10.63
H1547-2	AA	1	\$	10.63	\$	10.63
H1550-2	CT	1	\$	10.01	\$	10.01
H2034-2	B	2	\$	2.18	\$	4.36
H2035-2	A	1	\$	2.86	\$	2.86
H2036-2	A	1	\$	2.86	\$	2.86
H2090-2	AA	1	\$	2.62	\$	2.62
H2093-2	AT	2	\$	2.29	\$	4.58
H2100-2	C	1	\$	4.90	\$	4.90
H2101-2	AA	2	\$	4.88	\$	9.76
H2102-2	AA	2	\$	4.88	\$	9.76
H2104-2	AAT	2	\$	6.48	\$	12.96
H2106-2	CT	1	\$	5.23	\$	5.23
H2107-2	BT	1	\$	5.23	\$	5.23
H2108-2	A	2	\$	4.39	\$	8.78
H2117-2	A	1	\$	2.45	\$	2.45
H2148-2	C	2	\$	1.35	\$	2.70
H2508	B	1	\$	12.47	\$	12.47
H2509	B	1	\$	12.47	\$	12.47
H2514	AA	0	\$	9.26	\$	-
H2515	AA	1	\$	9.26	\$	9.26
H2528	A	2	\$	11.27	\$	22.54
H2529	A	1	\$	11.27	\$	11.27
H2532	B	1	\$	12.21	\$	12.21
H2534	B	1	\$	11.27	\$	11.27
H2535	B	1	\$	11.27	\$	11.27
H2540	CT	1	\$	9.75	\$	9.75
H2541	CT	1	\$	9.75	\$	9.75
H2544	AAT	1	\$	10.42	\$	10.42
H2545	AAT	1	\$	10.42	\$	10.42
H2572	FWT	1	\$	15.88	\$	15.88

MANGIS MOTOR SERVICE CO.

H2578	B	1	\$	12.41	\$	12.41
H2579	B	1	\$	12.41	\$	12.41
H2580	AAT	1	\$	15.92	\$	15.92
H2581	AAT	1	\$	15.92	\$	15.92
H2584	AT	3	\$	14.87	\$	44.61
H2585	AT	3	\$	14.87	\$	44.61
H2588	AAT	1	\$	22.81	\$	22.81
H2589	AAT	2	\$	22.81	\$	45.62
H2590	BT	2	\$	15.67	\$	31.34
H2591	BT	1	\$	15.67	\$	15.67
H2592	AA	1	\$	10.45	\$	10.45
H2593	AA	1	\$	10.45	\$	10.45
H2596	W	1	\$	13.73	\$	13.73
H2597	W	2	\$	13.73	\$	27.46
H2598	AA	1	\$	13.32	\$	13.32
H2599	AA	1	\$	13.32	\$	13.32
H2604	B	1	\$	9.99	\$	9.99
H2605	B	1	\$	9.99	\$	9.99
H2608	OBS	1	\$	9.00	\$	9.00
H2609	OBS	1	\$	9.00	\$	9.00
H2622	C	1	\$	13.48	\$	13.48
H2623	AA	1	\$	13.00	\$	13.00
H2632	B	1	\$	18.24	\$	18.24
H2633	B	1	\$	18.24	\$	18.24
H2644	B	1	\$	12.28	\$	12.28
H3200-2	C	2	\$	4.09	\$	8.18
H4003-2	AA	1	\$	4.68	\$	4.68
H4017-2	FW	1	\$	4.60	\$	4.60
H4018-2	AAT	2	\$	5.30	\$	10.60
H4020-2	B	1	\$	4.95	\$	4.95
H4029-2	W	1	\$	4.58	\$	4.58
H4030-2	AA	1	\$	4.97	\$	4.97
H4035-2	FW	0	\$	4.66	\$	-
H4043-2	CT	1	\$	4.73	\$	4.73
H4067-2	C	1	\$	4.66	\$	4.66
H4070-2	FW	2	\$	4.95	\$	9.90
H4074	CT	1	\$	4.89	\$	4.89
H4094-2	A	1	\$	4.89	\$	4.89
H4095-2	C	1	\$	3.68	\$	3.68
H4096-2	AA	1	\$	4.48	\$	4.48
H4101 USEH4094-2	OBS	1	\$	4.42	\$	4.42
H5002-2	A	2	\$	2.97	\$	5.94
H5004-2	AA	2	\$	5.89	\$	11.78
H5007-2	CT	3	\$	6.67	\$	20.01
H5010-2	CT	1	\$	5.04	\$	5.04
H5015-2	A	1	\$	6.08	\$	6.08
H5016-2	C	1	\$	5.94	\$	5.94
H5017-2	W	2	\$	7.43	\$	14.86
H5019	B	4	\$	3.33	\$	13.32
H5021-2	C	2	\$	3.65	\$	7.30
H5022-2	OBS	2	\$	4.00	\$	8.00

MANGIS MOTOR SERVICE CO.

H5025	A	2	\$	5.21	\$	10.42
H5029-2	OBS	1	\$	6.54	\$	6.54
H5030-2	A	3	\$	8.10	\$	24.30
H5031-2	AAT	1	\$	11.01	\$	11.01
H5044	AT	2	\$	9.89	\$	19.78
H5049	C	1	\$	8.54	\$	8.54
H5050-2	B	2	\$	3.97	\$	7.94
H5103-2	A	0	\$	2.87	\$	-
H5107	W	1	\$	5.75	\$	5.75
H5109	W	8	\$	1.92	\$	15.36
H5115-2	FW	4	\$	2.17	\$	8.68
H5201-2	AA	2	\$	1.91	\$	3.82
H5202-2	A	1	\$	1.89	\$	1.89
H5213-2	FW	1	\$	5.45	\$	5.45
H5370-2	C	3	\$	3.54	\$	10.62
H5371-2	A	4	\$	2.12	\$	8.48
H5372-2	B	4	\$	2.04	\$	8.16
H5373	B	1	\$	3.23	\$	3.23
H5374-2	C	4	\$	3.23	\$	12.92
H5375-2	C	3	\$	3.23	\$	9.69
H5408-2	AA	4	\$	1.72	\$	6.88
H5418-2	B	9	\$	1.10	\$	9.90
H5420	BT	1	\$	2.10	\$	2.10
H5424	B	1	\$	1.23	\$	1.23
H5431-2	AA	1	\$	2.11	\$	2.11
H5432-2	FW	1	\$	2.56	\$	2.56
H5500	AA	2	\$	3.97	\$	7.94
H5510	W	3	\$	9.58	\$	28.74
H5514	W	2	\$	6.39	\$	12.78
H5515	BT	5	\$	10.90	\$	54.50
H5516	AA	2	\$	6.30	\$	12.60
H5519	AT	1	\$	11.85	\$	11.85
H5524	B	2	\$	5.91	\$	11.82
H5529	AT	1	\$	12.30	\$	12.30
H5537	W	2	\$	7.08	\$	14.16
H5538	C	4	\$	11.27	\$	45.08
H5541	A	4	\$	9.83	\$	39.32
H5544	A	2	\$	9.22	\$	18.44
H5545	OBS	2	\$	9.00	\$	18.00
H5547-2	C	3	\$	2.86	\$	8.58
H5548-2	BT	3	\$	11.92	\$	35.76
H5552-2	BT	0	\$	6.49	\$	-
H5562-2	B	2	\$	2.72	\$	5.44
H5567	B	3	\$	5.73	\$	17.19
H5584	AAT	0	\$	3.89	\$	-
H5587	A	0	\$	14.48	\$	-
H5600	AA	4	\$	6.47	\$	25.88
H5603	B	1	\$	12.78	\$	12.78
H5604	AA	0	\$	2.47	\$	-
H5610	AA	0	\$	4.91	\$	-
H7008	W	1	\$	9.05	\$	9.05

MANGIS MOTOR SERVICE CO.

H7017	BT	1	\$	8.83	\$	8.83
H7018	BT	1	\$	8.95	\$	8.95
H7028	A	1	\$	8.72	\$	8.72
H7041	C	2	\$	9.22	\$	18.44
H7042	AT	1	\$	14.34	\$	14.34
H7044-2	OBS	1	\$	9.00	\$	9.00
H7045	C	3	\$	8.97	\$	26.91
H7046	AAT	3	\$	8.91	\$	26.73
H7055	AAT	1	\$	9.58	\$	9.58
H7064	B	1	\$	8.60	\$	8.60
H7067	B	1	\$	9.05	\$	9.05
H7070 USE H7269	OBS	1	\$	7.43	\$	7.43
H7071	AAT	0	\$	9.48	\$	-
H7072 USE H7268	OBS	1	\$	7.80	\$	7.80
H7128	W	1	\$	10.22	\$	10.22
H7137	CT	1	\$	9.91	\$	9.91
H7146	AT	0	\$	13.97	\$	-
H7152	C	1	\$	8.56	\$	8.56
H7157 USE H7246	0-2	3	\$	8.68	\$	26.04
H7161	W	1	\$	9.22	\$	9.22
H7165	B	1	\$	8.87	\$	8.87
H7166	A	1	\$	8.19	\$	8.19
H7167	W	3	\$	8.91	\$	26.73
H7169	A	2	\$	12.09	\$	24.18
H7170	AAT	1	\$	7.86	\$	7.86
H7209	AT	0	\$	12.04	\$	-
H7246	A	1	\$	8.68	\$	8.68
H7266 USE H7268	OBS	2	\$	7.80	\$	15.60
H7269	AA	1	\$	7.43	\$	7.43
H7270	A	1	\$	8.91	\$	8.91
H7271	X	1	\$	8.19	\$	8.19
H7286	B	1	\$	7.68	\$	7.68
H15001-2	FWI	4	\$	2.92	\$	11.68
H15002-2	WI	4	\$	2.81	\$	11.24
H15009-2	CI	4	\$	2.67	\$	10.68
H15351-2	AI	1	\$	2.50	\$	2.50
H15352-2	FWI	2	\$	2.37	\$	4.74
H15501-2	CI	3	\$	6.76	\$	20.28
H15504-2	CI	4	\$	6.82	\$	27.28
					\$	-
H15506-2	CI	4	\$	3.37	\$	13.48
H15507-2	BI	4	\$	4.17	\$	16.68
H15522-2	BI	4	\$	5.12	\$	20.48
H15524-2	WI	4	\$	5.63	\$	22.52
H15530-2	CI	4	\$	2.76	\$	11.04
H15532-2	WI	4	\$	8.19	\$	32.76
H15533-2	XI	4	\$	4.97	\$	19.88
H15534	CI	4	\$	5.01	\$	20.04
H15535-2	WT	4	\$	7.29	\$	29.16
H15536-2	CTI	4	\$	4.29	\$	17.16
H15539-2	CI	3	\$	3.66	\$	10.98

MANGIS MOTOR SERVICE CO.

H15546		FWI	4	\$	5.85	\$	23.40
H15550-2		CI	2	\$	4.01	\$	8.02
H15638		AI	1	\$	15.26	\$	15.26
H15700		B	1	\$	7.66	\$	7.66
H16033		AI	1	\$	9.99	\$	9.99
H17104		FWI	2	\$	10.06	\$	20.12
H17105		WI	2	\$	11.16	\$	22.32
H17107		WI	2	\$	13.48	\$	26.96
H17111		WTI	2	\$	10.86	\$	21.72
H17112		WI	2	\$	13.61	\$	27.22
H17115		XI	2	\$	10.24	\$	20.48
H17116		XI	2	\$	7.68	\$	15.36
H17122		WI	2	\$	12.09	\$	24.18
H17137		BI	1	\$	11.65	\$	11.65
H17141		WI	2	\$	11.86	\$	23.72
H17142		CI	1	\$	9.22	\$	9.22
H17158		WI	3	\$	7.37	\$	22.11
H17159	CHEMICAL	FWI	2	\$	9.48	\$	18.96
H17162		WI	2	\$	7.82	\$	15.64
H17163		WI	3	\$	7.84	\$	23.52
H17184		WI	3	\$	8.10	\$	24.30
H17187		CI	2	\$	11.82	\$	23.64
H17211		XI	1	\$	8.50	\$	8.50
						\$	2,921.02
						\$	2,921.02

BAF AS		NA	1	\$	5.55	\$	5.55
						\$	5.55

OBSOLETE WHEEL CYLINDERS MIXTURE OF EIS AND WAGNER

EW4156		OBS	1	\$	20.00	\$	20.00
EW9095		OBS	4	\$	20.00	\$	80.00
EW9510		OBS	1	\$	20.00	\$	20.00
EW9511		OBS	1	\$	20.00	\$	20.00
EW9679		OBS	2	\$	20.00	\$	40.00
EW15427		OBS	3	\$	20.00	\$	60.00
EW15428		OBS	3	\$	20.00	\$	60.00
EW16870		OBS	2	\$	20.00	\$	40.00
EW16871		OBS	1	\$	20.00	\$	20.00
EW18435		OBS	4	\$	20.00	\$	80.00
EW18436		OBS	4	\$	20.00	\$	80.00
EW23551		OBS	1	\$	20.00	\$	20.00
EW23552		OBS	1	\$	20.00	\$	20.00
EW34228		OBS	1	\$	20.00	\$	20.00
EW34229		OBS	1	\$	20.00	\$	20.00
EW34476		OBS	1	\$	20.00	\$	20.00
					SUBTOTAL	\$	620.00
					GRAND TOTAL	\$	620.00
					INVENTORY DATE 8\24\01	\$	16,740.70

MANGIS MOTOR SERVICE CO.

MANGIS MOTOR SERVICE CO.

MANGIS MOTOR SERVICE CO.

MANGIS MOTOR SERVICE CO.

MANGIS MOTOR SERVICE CO.

MANGIS MOTOR SERVICE CO.

MANGIS MOTOR SERVICE CO.

MANGIS MOTOR SERVICE CO.

MANGIS MOTOR SERVICE CO.

MANGIS MOTOR SERVICE CO.

MANGIS MOTOR SERVICE CO.

MANGIS MOTOR SERVICE CO.

MANGIS MOTOR SERVICE CO.

MANGIS MOTOR SERVICE CO.

